5/13

Split

DART AEROSPACE LTD	Work Order:	22516
Description: Bracket Assembly	Part Number:	D2804-042
Dwg: D2804 Rev. B	Qty:	5 20
		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler Dwg not required	A	05.02.23	
2	GA	Press D2805-2 into arm as per Dwg D2804 Pick: Oty Part Number Description Batch 1 D2804-2 Bracket Backet Backet 1 D2805-2 Stop Backet Backet 1 D2809 Bushing Backet Backet	SB	65/03/23	30
3	QC5	Inspect work to Step 2	180	2503-23	203
4	FP	Powder Coat Gloss White (Ref: 4.3.5.1) as per QSI 005 4.3	5.G	05/03/24	265
5	QC3	Inspect Powder Coat	1	S 03 3	4 20
6	GA	Press D2809 into arm as per Dwg D2804	SR	05/02/28	200
7	GA (1952,016 3 (Pus. 3.28	Spray LPS-3 on Bolt Shaft, not on thread as per Dwg D2804 Pick: Oty Part Number Description Batch 2 AN3C16A Bolt MIDAU 2 MS21042L3 Nut (or -3) MIGSU 4 NAS1515H3 Washer MIGSU A/R LPS-3 Corrosion Spray MIGSU	50	65/03/23	30 5
8	GA	Assemble as per Dwg D2804.	SIS	05/03/29	203
9	QC5	Inspect work to Step 8	2	05.03.25	20
10	ST	Identify and Stock	SB	05/2/29	5
11	AC	Cost / part: 5 8.90	5 45	0.5-04-01	5
12	DC	Close W/O 58.90 Inspect Level 21	W	05.04.05	5

Rev	Date	Change	Revised By	Approved	
Α	00.11.09	New Issue	EC,		
В	00.11.15	Revise pick list	EC	EC	
С	01.03.02	Added D2809 to pick list	EC	,	
D	01.04.26	Reformat	EC	7.1	
E	05.02.22	Revised Step 7	KJ/JLM (111	

RELEASED